

Crush Damage Profile 1 – subject vehicle scanned using Riegl VZ-400



Exemplar vehicle scanned by Riegl VZ-400



Scale 1:20  
0 1 2 US-ft

Project: HYUNDAI EXEMPLAR  
Location: N 32°47'49.6856", E -116°57'43.1167"  
Date: 2015-04-30 12:52:37  
vehicle scan 04229015

Subject vehicle overlaid on Exemplar in RiSolve to measure actual structural change.

